

1 OF 33 BATHROOMS



ESCAPING WATER BREAKS
DOWN THE VINYL ADHESIVE



ACRYLIC MEMBRANE



NAIL THROUGH WATER SERVICE



NO WATERPROOFING ONTO
THE WATER STOP



CORRODED STEEL DOOR JAMBS



BREAKING UP THE FLOOR TILES



PVC BEND NOT GLUED





REMOVING ROTTED TIMBERS



CREATING NEW FALLS IN THE SUBSTRATE



INSTALLING THE NEW SHEET PVC MEMBRANE & S/S "Z" FLASHING



SLIP SHEET & REINFORCING MESH INSTALLED



TIMBER REPLACED AND WALLS REINFORCED



APPLYING A MODIFIED CEMENT SCREED TO SMOOTH OUT THE FLOOR



FLOOD TESTING OUR WORK



NEW TOPPING WITH 1:60 GRADE TO NEW FLOOR WASTE



✓ WALLS RELINED WITH PENETRATIONS & JUNCTIONS SEALED



✓ GROUTING FINISHED WITH VERTICAL JUNCTIONS TO BE CAULKED



✓ VINYL FLOOR COVERING INSTALLED



✓ NEW PAN IS INSTALLED



✓ WALLS ARE TILED FROM THE BORDER DOWN TO THE "Z" FLASHING



✓ LEVELLING TOPPING APPLIED FOR VINYL FLOOR COVER



✓ PC ITEMS REINSTALLED IN THE ORIGINAL POSITIONS



✓ A GOOD CLEAN & THIS BATHROOM IS RECOMMISSIONED

